

9/9

0800 Antan started
 1000 " stopped - antan ✓

			{ 1.2700	9.037 847 025
				9.037 846 995 connect
13 ⁰⁰	MC (032)	MP - MC	1.982147000	2.130476415 (3)
	(033)	PRO 2	2.130476415	4.615925059(-2)
		connect	2.130676415	

Relays 6-2 in 033 failed special speed test
 in relay " 10.00 test.

Relay
 2145
 Relay 3376

1100 Started Cosine Tape (Sine check)
 1525 Started Mult + Adder Test.

1545



Relay #70 Panel F
 (moth) in relay.

First actual case of bug being found.
~~1630~~ Antan started.
 1700 closed down.